


EXPLANATION

- ⊗ Sample Location
- - - Approximate Extent of Excavation Beneath Tanks 2 and 6


Note:
Tank numbers, except 100, from LTE, 1999. Tank 100 (empty tank) removed by Hurricane Ike storm surge in September 2008. Verification samples collected in January 2011 after all tanks removed. Locations are approximate.

Source of photo: H-GAC, Texas aerial photograph, 2006.

DRAFT



Approx. Scale in Feet



GULFCO MARINE MAINTENANCE
FREEPORT, BRAZORIA COUNTY, TEXAS

Figure 2

FORMER AST TANK FARM VERIFICATION SAMPLE LOCATIONS

PROJECT: 1597

BY: ZGK

REVISIONS

DATE: FEB., 2011

CHECKED: EFP

PASTOR, BEHLING & WHEELER, LLC
CONSULTING ENGINEERS AND SCIENTISTS